

CLIENT/COMPANY	KWANTAS CORPORATION BERHAD AUDIT (KWANTAS OIL SDN BHD) AUDIT NO. 401/19				
ADDRESS	K-63-3rd Floor, Signature Office, KK Times Square, Off Coastal Highway, 88100 Kota Kinabalu, Sabah.				
MILL UNIT(S)	MEWAH PALM OIL MILL : 60 MT/HR				
TYPE OF ASSESSMENT	Main Audit				
GROUP MANAGER	Mr. Badrul Bin Mohd. Niza	am			
EMAIL ADDRESS	mohd.badrul@kwantas.co	m.my			
WEB PAGE	www.kwantas.com.my				
AUDIT STANDARD(S)	MS 2530-4:2013 - General principles for Palm Oil Mills				
AUDIT SCOPE	Provision of 60 mt/hr of Sustainable Palm Oil Mill				
AUDIT DATE	17 <sup>th</sup> – 18 <sup>th</sup> October 2019				
PREVIOUS AUDIT DATE	20 <sup>th</sup> - 21 <sup>st</sup> May 2019				
NEXT AUDIT DATE	1st Surveillance tentatively plan on <b>September 2019</b>				
OTHER CERTIFICATION HELD	ISO 9001 : 2015				
CERTIFICATE VALIDITY	06/11/2019 to 05/11/2024				
	LEAD AUDITOR	En. Mohd Isa Ha	sim (ISA)		
AUDITOR TEAM MEMBERS	AUDITOR	En. Basran Ab. H	lamid (BAH)		
	AUDITOR IN TRAINING	En. Hamsah Sula	aiman (HMS)		

These are your certification details.

Please inform us immediately if amendments are required.

## **Audit Conclusion**

Based on the documentation reviewed, records sampled, site visit and interview with relevant personnel during this **Stage 2** Audit, we conclude that **KWANTAS CORPORATION BERHAD (KWANTAS OIL SDN BHD)** has effectively implemented its Malaysian sustainable Palm Oil system in accordance to the **MS 2530-4:2013** requirements in line with the organization procedure & policy for the above mention scope

### Recommendation

The audit team has agreed to recommend **KWANTAS CORPORATION BERHAD (KWANTAS OIL SDN BHD)** to be awarded with **MS 2530-4:2013 Certifications** based on applied scope subject to review by Certification Approval Panel

CAS 16-02-MSPO Page 1 of 9



Lead Auditor	Mohd Isa Hasim	Signature	mofto lsa	Date	18/10/2019

#### **EXECUTIVE SUMMARY**

The Stage 2 audit was satisfactorily conducted to evaluate the MSPO implementation of MSPO 2530 Part 4 (Palm Oil Mill). The management is a wholly own company of KWANTAS CORPORATION BERHAD (KWANTAS OIL SDN BHD) which located 1.5 hours from Lahad Datu. The company has various businesses and one of the core business in Oil Palm plantation.

NIOSH Certification is an accredited certification body by Standards Malaysia which providing a comprehensive certification and inspection services mainly for management system of occupational safety & health, environmental, quality and MSPO for various industries. The **Stage 2** audit have been satisfactorily conducted by NIOSH Certification on **17**<sup>th</sup> **– 18**<sup>th</sup> **October 2019**.

During the audit closing meeting held on 18<sup>th</sup> October 2019 at meeting room, the overall results of the audit are as follows:

a. Major Nonconformity Report (NCR) : NONE (0)
 b. Minor Nonconformity Report (NCR) : NONE (0)
 c. Opportunities for Improvement (OFI) : FIVE (5)

CAS 16-02-MSPO Page **2** of **9** 



## ASSESSMENT TEAM MEMBER

Lead Auditor	Mr. Mohd Isa Hasim As a holding professional certificated 1st grade Steam Engineer, Lead Auditor MSPO MS2530, Lead Auditor ISO 9001:2015, Safety Officer (SHO) NIOSH, Authorized Entry Standby Person (AESP) NIOSH, Competent Person Schedule Waste (CePSWaM) DOE. Currently join a team between Certification Body as aMSPO Auditor since 2015 until now 2018. Current achievement he had got certification for Train The Trainer (TTT) from NIOSH and also (TTT) from HRDF.He has experience working in plantation industry which is background in palm oil mill as an Mill Engineer. Expertise in palm oil mill processing, implementation good mill practice in mill organization and maintain on legal compliance for safety, health and environment. He shows a good communicate between his cooperate team members during develop the documentation on Roundtable Sustainable Palm Oil (RSPO). Lastly, he has demonstrated leadership skill within palm oil mill organization with lead a team until successful achieving the certification of RSPO.
Auditor	En. HamsahSulaiman  He holds Master in Plantation Management & bachelor's degree in Organization Management from University Science Malaysia (USM) in 2005. He has 15 years working experience of managing oil palm plantations with expertise in Good Agricultural Practices (GAP) including Integrated Pest Management (IPM), Labour & Logistics Management. He is experienced with RSPO, MSPO and ISCC requirements for certification from all these various organizations. He successfully completed the Lead Auditor course for ISO 9001, ISO 14001 & ISO 45001 and Lead Auditor MSPO MS 2530:2013 & MS SCCS. He had been involved in MSPO auditing since 2018 in various companies in Malaysia. Able to communicate in Bahasa Malaysia, Bahasa English and Local Language.
Auditor	En. Basran Ab Hamid  Basran Ab Hamid hold a Degree From University Malaysia Sabah in International Business with more than 5 years working experience in plantation company and skills in Good Agricultural Practices (GAP) and involved in Safety and Health Plantation programme. Fully trained in similar agriculture certification programs such as MSPO. Completed and certified MSPO Auditor Course in January 2019 held by Niosh Certification. He attended Integrated Management System (IMS) conducted by Platinum Shauffman Veritas (PSV) Certification in December 2018. He able to speak and understand Bahasa Malaysia and English

CAS 16-02-MSPO Page **3** of **9** 



#### **AUDIT METHODOLOGY & AUDIT PROGRAMME**

The assessment was conducted involving palm oil mill under Kwantas Mewah POM. The minimum manday has been justified as per ABC-OPMC 2 (Audit Duration for CB Operating Oil Palm Management Certification under MSPO scheme). The audit were cover documentation and records review, physical mill observation covering all processes, workshop, chemicals store, effluent ponds, stakeholders consultation, interview with internal & external stakeholders, mill workers and contractors.

#### **SUMMARY AUDIT FINDINGS**

During the audit closing meeting held on 18 October 2019, the overall results of the audit are as follows:

The following items represented positive observations by the audit team:

- 1. Commitment Internal MSPO Team
- 2. Good understanding on the requirement of MSPO
- 3. Good of filing system on MSPO Documentation

The overall results of the audit are as follows:

d. Major Nonconformity Report (NCR) : NONE (0)
e. Minor Nonconformity Report (NCR) : NONE (0)
f. Opportunities for Improvement (OFI) : FIVE (5)

\*The grading of nonconformity (Major / Minor) is based on ISO/IEC 17021:2015 guidelines.

CAS 16-02-MSPO Page 4 of 9



## COMPANY BACKGROUND

Mewah Palm Oil Mill is located about 100KM from Lahad Datu. It was commissioned on the 15<sup>th</sup> of May 2000, with designed capacity at 60MT FFB/Hour. Apart from receiving crop from Mewah 1 Estate & Mewah 2 Estate, MPOM is also purchasing vicinity smallholder FFB. Since its commissioning, the mill has been producing good quality CPO and Palm Kernel that conforming to commercial specification. It is with the aspiration for consistent excellence of our products that our team strives to achieve MSPO for the Mewah Palm Oil Mill. The mill operates in line with the policies and views of KWANTAS OIL SDN BHD. The mill manager has been empowered to manage the overall mill operations and shall act as top management on MSPO requirement.

## **DETAILS OF MILL UNIT (S)**

NO	NAME	ADDRESS OF MILL	MILL CAPACIT Y	GPS COORDINATE	TOTAL MILL AREA (HA)
1	Mewah Palm Oil Mill	Mewah Palm Oil Mill, KM 70 Tabung Tentera Junction Jalan Lahad Datu-Sandakan, Sg.Koyah 91120 Lahad Datu, Sabah	60mt/hr	5.254414 117.960058	2439 HA

#### **MPOB LICENSE DETAILS**

	02 2.02.002 22.0020					
NO	MILL NAME	MPOB LICENSE NO.	SCOPE OF ACTIVITY	EXPIRY DATE		
1	Mewah Palm Oil Mill	500301904000	Menjual dan Mengalih FFB,PK,CPO,SPO Membeli dan Mengalih FFB Menyimpan PK,CPO,SPO Mengilang FFB Mengalih PPO,CPKO,PPKO	31/07/2019		

#### **MILL PROCESSING DATA**

Supply Base		essing and Produ al Previous Year			_		
	FFB Processed (MT)	CPO Production (MT)	PK Production (MT)	FFB Processed (MT)	CPO Production (MT)	PK Production (MT)	
Supply Base a. Own Supply b. Other Supply	139,490.51	28,507.69	6,810.06	26,263.05	5226.00	1310.78	
TOTAL	139,490.51	28,507.69	6,810.06	26,263.05	5226.00	1310.78	
Conversion Rate		OER:20.44%	KER:4.88%		OER:19.90%	KER:4.99%	

CAS 16-02-MSPO Page 5 of 9



## **LOCATION AND MAP**




FIGURE : MILL LAYOUT

CAS 16-02-MSPO Page **6** of **9** 



## **LOCATION AND MAP**




FIGURE: MILL LOCATION

CAS 16-02-MSPO Page **7** of **9** 



### Review and follow-up on previous audit findings

All Areas of Concern raised during the previous audit found has been addressed adequately.

#### **Stakeholders Consultation Session**

Stakeholder consultation began with notification of upcoming assessment by official letter to identified stakeholders. Emails, phone call and official letter were sent to applicable interested stakeholders. Audit team then visited some stakeholders to obtain positive / negative information or any issues in connection with estate and mill management. Among stakeholders contacted included external & internal:

Government agency / Smallholder / Supplier / Contractor / Internal Stakeholder

The agenda of discussion including legal compliance, environmental protection, biodiversity conservation, safety & social responsibility and development of community. There is no issue been raised up during stakeholder consultation. However, good finding and request recorded as following below:

#### External Stakeholder

- Good relationship stakeholder between estate management
- Good communication and cooperation between estate management
- Good understanding from stakeholder regarding of implementation MSPO

#### Name & Category Stakeholder

No	Name	Organisation	Stakeholder
1	Mr. Isnaidy Syarifuddin	CPO Transporter	External
2	Mr. Hasanuddin	Smallholder	External
3	Mr. Bahar	Smallholder	External
4	Mr. Arripuddin	Smallholder	External
5	Ms. Juraidah Hairin	Klinik Kesihatan	External
6	Ms. Kamaria Karim	Klinik Kesihatan	External

All positive and negative inputs from stakeholders has been discussed with management of **KWANTAS MEWAH POM** with proper justification and adequate action plan by the management team to address the issue.

CAS 16-02-MSPO Page 8 of 9



Others NIL

#### **Disclaimer**

NIOSH Certification provides services which are designed to determine whether the referenced Management System of the client:

- a) complies with the relevant (mentioned) Standard; and
- b) has been properly implemented and maintained.

Audits are based on random sampling techniques and non conformances may exist which did not become apparent during the audit.

NIOSH Certification does not provide any advice on compliance with any legislation, regulation, or standards. All audit reports and other documentation provided by NIOSH Certification, are given in good faith and in reliance on the accuracy and completeness of the information provided by the client. No responsibility is accepted to any third party that may rely in whole or in part on the content of this report, to the extent permitted by Law.

- End of Audit Report -

CAS 16-02-MSPO Page 9 of 9

CONFIDENTIAL